

2017 City Ditch Inventory

<u>US Structure</u>	<u>DS Structure</u>	<u>Conduit Rec #</u>	<u>Length</u>	<u>Last Inspection</u>	<u>Overall Condition Text</u>
AGM_02058	IMS_1123	1851	138.6238774	11/16/2017	Good
AGM_02280	AGM_02326	2080	450.1018308	11/16/2017	Good
AGM_06063	AGM_06065	4820	36.85454948	11/16/2017	Good
AGM_06086	AGM_06064	4826	33.32078334	11/16/2017	Good
AGM_11032	AGM_11033	8555	15.22425896	11/21/2017	Poor
AGM_11034	AGM_11035	8556	15.93568893	11/21/2017	Poor
AGM_11036	AGM_11035	8558	29.22061982	11/21/2017	Good
AGM_06485	AGM_06459	10014	119.5920688	11/20/2017	Good
AGM_06458	AGM_06459	10032	149.178952	11/20/2017	Good
AGM_06459	AGM_06448	10033	8.55680431	11/20/2017	Good
AGM_07573	AGM_07574	10239	74.13942637	11/20/2017	Good
AGM_15961	AGM_15962	13196	8.61707576	11/20/2017	Fair
AGM_14989	AGM_15008	14537	44.50353268	11/20/2017	Good
AGM_14998	AGM_15007	14543	42.6673268	11/20/2017	Good
AGM_15007	AGM_14997	14558	4.11224962	11/20/2017	Good
AGM_15008	AGM_15046	14612	2.67473373	11/20/2017	Good
AGM_15050	AGM_15083	14618	17.55689003	11/20/2017	Good
AGM_15083	AGM_15039	14620	257.986602	11/20/2017	Good
AGM_09054	AGM_09052	23319	35.85464042	11/21/2017	Good

2017 City Ditch Inventory

<u>US Structure</u>	<u>DS Structure</u>	<u>Conduit Rec #</u>	<u>Length</u>	<u>Last Inspection</u>	<u>Overall Condition Text</u>
AGM_09055	AGM_09052	23320	63.29326427	11/21/2017	Good
AGM_09053	AGM_09052	23321	4.17132602	11/21/2017	Good
AGM_09060	AGM_09059	23322	24.40036286	11/21/2017	Good
AGM_27025	AGM_27026	24514	147.627106	11/20/2017	Fair
AGM_08733	AGM_08723	24593	782.504648	11/21/2017	Fair
AGM_24541	AGM_24540	24944	7.05576676	11/20/2017	Good
AGM_22338	AGM_22337	25920	44.00954348	11/20/2017	Fair
AGM_22472	AGM_22339	26055	77.38499472	11/20/2017	Good
AGM_22476	AGM_22475	26060	46.48584585	11/20/2017	Good
AGM_22478	AGM_22477	26061	113.4843478	11/20/2017	Fair
AGM_18420	AGM_18489	27141	2.42818628	11/20/2017	Fair
AGM_18489	AGM_18419	27142	2.86494691	11/20/2017	Fair
AGM_21778	AGM_21680	27363	88.93106619	11/20/2017	Good
AGM_21767	AGM_21768	27465	15.41687081	11/20/2017	Good
AGM_21779	IMS_2976	27479	47.0427965	11/20/2017	Good
AGM_21681	AGM_21769	27480	251.5688978	11/20/2017	Good
AGM_14732	AGM_14733	28868	258.3299113	11/20/2017	Fair
AGM_14734	AGM_14736	28870	27.25269953	11/20/2017	Fair
AGM_14760	AGM_14761	28880	54.63285443	11/20/2017	Good

2017 City Ditch Inventory

<u>US Structure</u>	<u>DS Structure</u>	<u>Conduit Rec #</u>	<u>Length</u>	<u>Last Inspection</u>	<u>Overall Condition Text</u>
AGM_14770	AGM_14788	28888	298.6691264	11/20/2017	Good
AGM_27424	AGM_27552	29591	416.9017423	11/20/2017	Fair
AGM_20944	AGM_20927	31079	8.87390564	11/17/2017	Good
AGM_20929	AGM_20944	31159	85.50973863	11/17/2017	Fair
AGM_20928	AGM_20944	31160	195.3095486	11/17/2017	Good
SSG_00888	AGM_02384	32719	110.76	11/16/2017	Good