

Structure Inventory Summary Report

10/31/2018
3:02 PM

Rec #:	Structure Number:	Basin:	Type:	Location:	Surface Type:	Rim Elevation:	Depth(ft):	Status:
765	IMS_765	Long Isl	Open	Right	Fair		1.50	Operational
1,259	IMS_1259	Marsh	Concrete Topped	Left	Good	0.00	4.25	Operational
2,314	IMS_2314	T4	Concrete Topped	Right	Good	0.00	0.00	Operational
3,486	IMS_3486	O13	Grated	Right	Good	0.00	2.53	Operational
4,291	OPT_4079	Long Isl				0.00	2.70	Operational
4,635	AGM_00109	Nancy					3.81	Operational
4,659	AGM_00059	Nancy					6.49	Operational
4,669	AGM_00086	Nancy					0.00	Operational
4,691	AGM_00150	Nancy					3.34	Operational
4,715	AGM_00035	Nancy					1.50	Not Found
4,723	AGM_00027	Nancy					4.20	Operational
4,779	AGM_00688	Nancy					1.50	Operational
4,785	AGM_00708	Nancy				0.00	2.97	Operational
4,802	AGM_00696	Nancy					3.41	Operational
4,823	AGM_00738	Nancy					3.80	Operational
4,829	AGM_00733	Nancy				0.00	3.78	Operational
4,836	AGM_00757	Nancy					2.00	Operational
4,837	AGM_00756	Nancy					1.66	Operational
4,871	AGM_00446	Nancy				0.00	5.21	Operational
4,873	AGM_00476	Nancy				0.00	2.15	Operational
4,967	AGM_00955	Long Isl					2.50	Operational
4,986	AGM_00974	Nancy				0.00	1.50	Buried
5,076	AGM_00329	Nancy					3.00	Operational
5,097	AGM_01023	Long Isl					2.70	Operational
5,141	AGM_01052	Long Isl					5.20	Operational
5,144	AGM_01080	Long Isl					3.80	Operational
5,231	AGM_00523	Nancy					4.60	Operational
5,238	AGM_00516	Nancy					1.50	Operational
5,242	AGM_00512	Nancy					1.50	Operational
5,251	AGM_00535	Nancy					3.61	Operational
5,257	AGM_00529	Nancy					4.31	Operational
5,274	AGM_00544	Nancy					2.00	Operational
5,283	AGM_00565	Nancy					2.00	Operational

Structure Inventory Summary Report

10/31/2018

3:02 PM

Rec #:	Structure Number:	Basin:	Type:	Location:	Surface Type:	Rim Elevation:	Depth(ft):	Status:
5,303	AGM_00577	Nancy					4.47	Operational
5,329	AGM_00616	Nancy					1.62	Operational
5,331	AGM_00614	Nancy					1.50	Operational
5,339	AGM_00638	Nancy					0.00	Operational
5,473	AGM_00219	Nancy					0.00	Operational
5,491	AGM_00231	Nancy					4.50	Operational
5,509	AGM_00245	Nancy					3.25	Operational
5,529	AGM_00254	Nancy					1.65	Operational
5,549	AGM_00202	Nancy					2.80	Operational
5,555	AGM_00273	Nancy					1.80	Operational
5,582	AGM_00163	Nancy					3.30	Operational
5,596	AGM_00181	Nancy					1.70	Operational
5,632	AGM_02034	Nancy					3.81	Operational
5,650	AGM_02052	Nancy					1.50	Operational
5,665	AGM_02067	Nancy					0.00	Not Found
5,670	AGM_02072	Nancy					2.61	Operational
5,677	AGM_02079	Nancy					3.21	Operational
5,687	AGM_02089	Nancy					0.00	Not Found
5,761	AGM_02186	Nancy					2.45	Operational
5,872	AGM_01215	Nancy					2.50	Operational
5,875	AGM_01218	Nancy					2.00	Operational
5,988	AGM_01329	Nancy					1.50	Operational
5,989	AGM_01330	Nancy					1.50	Operational
5,996	AGM_01402	Nancy					1.50	Operational
6,135	AGM_02238	Nancy					0.50	Operational
6,137	AGM_02194	Nancy					2.13	Operational
6,153	AGM_02241	Nancy					0.50	Operational
6,155	AGM_02243	Nancy					2.64	Operational
6,157	AGM_02245	Nancy					3.37	Operational
6,168	AGM_02256	Nancy					0.00	Operational
6,170	AGM_02258	Nancy					2.91	Operational
6,348	AGM_02437	Nancy					2.64	Operational
6,381	AGM_02470	Nancy					1.50	Operational

Structure Inventory Summary Report

10/31/2018

3:02 PM

Rec #:	Structure Number:	Basin:	Type:	Location:	Surface Type:	Rim Elevation:	Depth(ft):	Status:
6,386	AGM_02476	Nancy					1.91	Operational
6,387	AGM_02477	Nancy					1.50	Operational
6,402	AGM_02492	Nancy					1.50	Operational
6,408	AGM_02498	Nancy					0.00	Operational
6,457	AGM_02543	Nancy					2.79	Operational
6,464	AGM_02549	Nancy					2.62	Operational
6,490	AGM_01939	Nancy					1.50	Operational
6,523	AGM_01972	Nancy					1.50	Operational
6,524	AGM_01973	Nancy					0.00	Operational
6,561	AGM_01860	Nancy					2.50	Operational
6,569	AGM_01868	Nancy					8.25	Operational
6,574	AGM_01873	Nancy					2.25	Operational
6,594	AGM_01893	Nancy					2.50	Operational
6,609	AGM_01908	Nancy					2.00	Operational
6,613	AGM_01912	Nancy					2.00	Operational
6,619	AGM_01918	Nancy					1.50	Operational
6,735	AGM_01768	Long Isl					3.65	Operational
6,771	AGM_01496	Long Isl					2.00	Operational
6,774	AGM_01499	Long Isl					3.50	Operational
6,782	AGM_03362	Long Isl					4.11	Operational
6,783	AGM_01563	Nancy					1.25	Operational
6,784	AGM_01564	Nancy					2.28	Operational
6,948	AGM_01791	Long Isl					5.68	Operational
6,978	AGM_00768	Nancy					2.25	Operational
6,979	AGM_00769	Nancy					2.80	Operational
6,982	AGM_00772	Nancy					1.50	Operational
7,001	AGM_00791	Nancy					8.80	Operational
7,002	AGM_00792	Nancy					11.40	Operational
7,004	AGM_00794	Nancy					1.65	Operational
7,007	AGM_00797	Nancy					2.20	Operational
7,019	AGM_00809	Nancy					1.65	Operational
7,042	AGM_00832	Nancy					2.75	Operational
7,056	AGM_00845	Nancy					2.20	Operational

Structure Inventory Summary Report

10/31/2018

3:02 PM

Rec #:	Structure Number:	Basin:	Type:	Location:	Surface Type:	Rim Elevation:	Depth(ft):	Status:
7,057	AGM_00846	Nancy					1.50	Not Found
7,074	AGM_00862	Nancy					5.50	Operational
7,088	AGM_00874	Nancy					6.20	Operational
7,106	AGM_00895	Nancy					4.46	Operational
7,584	AGM_02958	Long Isl					9.64	Operational
7,754	AGM_03227	Nancy					2.00	Operational
7,759	AGM_03232	Nancy					1.15	Operational
7,761	AGM_03234	Nancy					2.00	Operational
7,763	AGM_03236	Nancy					4.10	Operational
7,831	AGM_03304	Nancy					2.50	Operational
7,839	AGM_03312	Nancy					2.00	Operational
7,845	AGM_03318	Nancy					2.00	Operational
7,858	AGM_03331	Nancy					1.50	Operational
7,859	AGM_03332	Nancy					1.50	Operational
7,889	AGM_03803	Long Isl					5.23	Operational
7,939	AGM_03819	Long Isl					2.00	Operational
7,943	AGM_03823	Long Isl					2.00	Operational
7,981	AGM_03861	Long Isl					1.50	Operational
8,018	AGM_03898	Long Isl					2.85	Operational
8,021	AGM_03901	Long Isl					1.50	Operational
8,203	AGM_04420	Long Isl					3.00	Operational
8,255	AGM_04471	Long Isl					5.16	Operational
8,260	AGM_04476	Long Isl					3.00	Operational
8,262	AGM_04478	Long Isl					1.50	Operational
8,264	AGM_04480	Long Isl					1.50	Operational
8,266	AGM_04482	Long Isl					1.50	Operational
8,268	AGM_04484	Long Isl					1.50	Operational
8,754	AGM_06316	Nancy					3.00	Operational
8,756	AGM_06318	Nancy					1.50	Buried
8,857	AGM_03506	Nancy					1.50	Operational
8,893	AGM_03574	Nancy					4.87	Operational
8,900	AGM_03597	Nancy					2.20	Operational
8,910	AGM_03623	Nancy					1.50	Operational

Structure Inventory Summary Report

10/31/2018

3:02 PM

Rec #:	Structure Number:	Basin:	Type:	Location:	Surface Type:	Rim Elevation:	Depth(ft):	Status:
8,920	AGM_03633	Nancy					2.00	Operational
9,157	AGM_03582	Nancy					2.50	Operational
9,219	AGM_07189	Long Isl					1.50	Operational
9,223	AGM_07193	Long Isl					2.30	Operational
9,236	AGM_07206	Long Isl					1.50	Operational
9,258	AGM_07228	Long Isl					2.30	Operational
9,281	AGM_07164	Long Isl					1.50	Operational
9,284	AGM_07167	Long Isl					2.97	Operational
9,297	AGM_07234	Long Isl					1.50	Buried
9,306	AGM_07243	Long Isl					5.70	Operational
9,308	AGM_07245	Long Isl					2.60	Operational
9,329	AGM_07073	Long Isl					0.00	Operational
9,349	AGM_07093	Long Isl					3.85	Operational
9,352	AGM_07096	Long Isl					4.63	Operational
9,360	AGM_07104	Long Isl					3.02	Operational
9,363	AGM_07107	Long Isl					2.00	Operational
9,365	AGM_07109	Long Isl					1.50	Operational
9,422	AGM_07312	Long Isl					1.50	Operational
9,463	AGM_06982	Long Isl					1.50	Operational
9,477	AGM_06996	Long Isl					2.70	Operational
9,482	AGM_07001	Long Isl					2.30	Operational
9,513	AGM_07032	Long Isl					2.68	Operational
9,516	AGM_07035	Long Isl					3.15	Operational
9,539	AGM_07058	Long Isl					0.00	Operational
9,541	AGM_07060	Long Isl					1.50	Operational
9,577	AGM_07756	Long Isl					0.98	Operational
9,587	AGM_07371	Long Isl					4.89	Operational
9,590	AGM_07374	Long Isl					4.87	Operational
9,592	AGM_07376	Long Isl					6.30	Operational
9,594	AGM_07378	Long Isl					5.15	Operational
9,665	AGM_07428	Long Isl					0.00	Operational
9,666	AGM_07429	Long Isl					3.07	Operational
9,683	AGM_07446	Long Isl					2.55	Operational

Structure Inventory Summary Report

10/31/2018

3:02 PM

Rec #:	Structure Number:	Basin:	Type:	Location:	Surface Type:	Rim Elevation:	Depth(ft):	Status:
9,686	AGM_07449	Long Isl					1.60	Operational
9,719	AGM_07379	Long Isl					0.00	Operational
9,740	AGM_07401	Long Isl					2.08	Operational
9,743	AGM_07404	Long Isl					3.19	Operational
9,778	AGM_08111	Long Isl					5.10	Operational
9,790	AGM_08123	Long Isl					1.50	Operational
9,795	AGM_08128	Long Isl					2.00	Abandoned
9,796	AGM_08129	Long Isl					3.15	Operational
9,798	AGM_08131	Long Isl					2.80	Operational
9,820	AGM_08153	Long Isl					0.00	Buried
9,849	AGM_08182	Long Isl					2.63	Operational
9,863	AGM_08196	Long Isl					3.40	Operational
9,866	AGM_08199	Long Isl					2.00	Operational
9,889	AGM_08222	Long Isl					1.50	Operational
9,961	AGM_07819	Long Isl					1.85	Operational
10,248	AGM_10146	T19					3.01	Operational
10,274	AGM_08481	Long Isl				0.00	3.06	Operational
10,290	AGM_08514	Long Isl				0.00	0.00	Not Found
10,292	AGM_08516	Long Isl				0.00	5.14	Operational
10,309	AGM_08519	Long Isl				0.00	0.00	Operational
10,331	AGM_08541	Long Isl				0.00	3.48	Operational
10,341	AGM_08551	Long Isl					2.60	Operational
10,343	AGM_08553	Long Isl				0.00	7.25	Operational
10,346	AGM_08556	Long Isl				0.00	6.25	Operational
10,364	AGM_08574	Long Isl				0.00	5.12	Operational
10,386	AGM_08596	Long Isl				0.00	1.50	Operational
10,426	AGM_08322	Long Isl				0.00	4.14	Operational
10,440	AGM_11336	T18				0.00	3.00	Operational
10,454	AGM_11319	T18				0.00	2.00	Operational
10,489	AGM_08312	Long Isl					2.68	Operational
10,527	AGM_08372	Long Isl					3.65	Operational
10,540	AGM_08385	Long Isl					6.30	Operational
10,561	AGM_08406	T19				0.00	2.68	Operational

Structure Inventory Summary Report

10/31/2018

3:02 PM

Rec #:	Structure Number:	Basin:	Type:	Location:	Surface Type:	Rim Elevation:	Depth(ft):	Status:
10,572	AGM_08417	T19				0.00	2.89	Operational
10,637	AGM_09852	Long Isl				0.00	2.68	Operational
10,671	AGM_09984	Long Isl					0.00	Operational
10,684	AGM_09997	Long Isl					3.15	Operational
10,697	AGM_10010	T18				0.00	4.13	Operational
10,712	AGM_10024	Long Isl				0.00	3.34	Operational
10,713	AGM_10025	Long Isl					5.01	Operational
10,759	AGM_09910	Long Isl				0.00	2.00	Operational
10,951	AGM_11323	Heards				0.00	2.10	Operational
10,969	AGM_11326	T18				0.00	0.00	Operational
10,972	AGM_11327	T18				0.00	24.00	Operational
11,006	AGM_11210	Heards				0.00	2.00	Operational
11,210	AGM_04714	Nancy					3.18	Operational
11,212	AGM_04729	Nancy					4.68	Operational
11,213	AGM_04730	Nancy					4.95	Operational
11,214	AGM_04731	Nancy					4.70	Operational
11,494	AGM_09789	Heards				0.00	7.90	Operational
11,549	AGM_10187	T19				0.00	2.74	Operational
11,553	AGM_10150	T19				0.00	2.00	Operational
11,559	AGM_10156	T19				0.00	0.00	Operational
11,615	AGM_11390	T18				0.00	1.25	Operational
11,652	AGM_10746	Long Isl				0.00	3.75	Operational
11,653	AGM_10747	Long Isl				0.00	4.00	Operational
11,749	AGM_10973	Long Isl				0.00	1.50	Operational
11,766	AGM_10780	Long Isl				0.00	1.50	Operational
11,784	AGM_10989	Long Isl				0.00	9.20	Operational
11,787	AGM_10992	Long Isl				0.00	5.10	Operational
11,813	AGM_11018	Long Isl				0.00	5.73	Operational
11,814	AGM_11019	Long Isl				0.00	6.23	Operational
11,817	AGM_11022	Long Isl				0.00	2.50	Operational
11,831	AGM_11036	Long Isl				0.00	2.00	Operational
11,832	AGM_11037	Long Isl				0.00	5.30	Operational
11,834	AGM_11039	Long Isl					0.00	Operational

Structure Inventory Summary Report

10/31/2018

3:02 PM

Rec #:	Structure Number:	Basin:	Type:	Location:	Surface Type:	Rim Elevation:	Depth(ft):	Status:
12,134	AGM_07516	Long Isl					1.25	Operational
12,136	AGM_07518	Long Isl					1.68	Operational
12,183	AGM_09707	O13					3.57	Operational
12,224	AGM_09673	O14					2.38	Operational
12,248	AGM_09698	O14					0.00	Operational
12,320	AGM_08707	T18					4.94	Operational
12,531	AGM_12461	Colewood				0.00	2.00	Operational
12,554	AGM_11956	T18				0.00	1.50	Operational
12,611	AGM_12013	T18				0.00	2.00	Operational
12,612	AGM_12014	T18				0.00	5.12	Operational
12,620	AGM_12022	T18				0.00	1.50	Operational
12,625	AGM_12027	T18				0.00	2.50	Operational
12,710	AGM_12112	T18				0.00	2.46	Operational
12,729	AGM_12131	T18				0.00	1.50	Operational
12,732	AGM_12134	T18				0.00	1.50	Operational
12,758	AGM_12160	T18				0.00	1.25	Operational
12,775	AGM_12177	T18				0.00	1.50	Operational
12,837	AGM_12239	T19				0.00	1.62	Operational
12,838	AGM_12240	T18				0.00	1.50	Operational
13,276	AGM_07619	Marsh					2.67	Operational
13,317	AGM_07660	Marsh					3.47	Operational
13,330	AGM_07673	Long Isl					4.00	Operational
13,332	AGM_07675	Long Isl					3.14	Operational
13,419	AGM_06728	Long Isl				0.00	0.00	Operational
13,420	AGM_06729	Long Isl					0.00	Operational
13,458	AGM_06769	Long Isl					1.00	Operational
13,464	AGM_06775	Long Isl					1.50	Operational
13,470	AGM_06781	Long Isl					1.50	Operational
13,479	AGM_06790	Long Isl					1.50	Operational
13,485	AGM_06796	Long Isl				0.00	2.50	Operational
13,521	AGM_06834	Long Isl					2.23	Operational
13,583	AGM_06883	Long Isl					3.05	Operational
13,603	AGM_06903	Long Isl					2.00	Operational

Structure Inventory Summary Report

10/31/2018

3:02 PM

Rec #:	Structure Number:	Basin:	Type:	Location:	Surface Type:	Rim Elevation:	Depth(ft):	Status:
13,604	AGM_06904	Long Isl					2.00	Operational
13,605	AGM_06905	Long Isl					2.00	Operational
13,606	AGM_06906	Long Isl					2.00	Operational
13,705	AGM_12773	O15				0.00	4.15	Operational
13,716	AGM_12784	O15				0.00	2.71	Buried
13,727	AGM_12795	T17				0.00	5.17	Operational
13,753	AGM_12821	O15				0.00	2.74	Operational
13,754	AGM_12822	O15				0.00	2.81	Operational
13,776	AGM_11440	Long Isl				0.00	2.50	Operational
13,777	AGM_11441	Long Isl				0.00	2.60	Operational
13,887	AGM_11532	Long Isl					1.50	Operational
13,995	AGM_11738	Long Isl				0.00	4.00	Operational
14,027	AGM_11631	Long Isl				0.00	2.00	Operational
14,049	AGM_11653	Long Isl					1.50	Operational
14,050	AGM_11654	Long Isl				0.00	3.00	Operational
14,051	AGM_11655	Long Isl				0.00	16.15	Operational
14,082	AGM_11686	Long Isl				0.00	2.00	Operational
14,190	AGM_11900	Long Isl				0.00	3.13	Operational
14,204	AGM_11916	Long Isl				0.00	3.00	Not Found
14,300	AGM_12605	Colewood				0.00	3.50	Operational
14,316	AGM_12618	Colewood				0.00	1.50	Operational
14,320	AGM_12621	Colewood				0.00	1.50	Operational
14,323	AGM_12623	Colewood				0.00	5.24	Operational
14,329	AGM_12626	Colewood				0.00	5.50	Operational
14,339	AGM_12634	Colewood				0.00	1.50	Operational
14,340	AGM_12635	Colewood				0.00	2.00	Operational
14,349	AGM_12580	Colewood				0.00	6.50	Operational
14,357	AGM_12647	Colewood				0.00	3.29	Operational
14,366	AGM_12653	Colewood				0.00	2.00	Operational
14,385	AGM_12669	Colewood				0.00	1.50	Operational
14,417	AGM_12695	Colewood				0.00	1.50	Operational
14,513	AGM_13530	O13				0.00	3.00	Operational
14,570	AGM_14083	T16					2.00	Operational

Structure Inventory Summary Report

10/31/2018

3:02 PM

Rec #:	Structure Number:	Basin:	Type:	Location:	Surface Type:	Rim Elevation:	Depth(ft):	Status:
14,592	AGM_14105	Colewood				0.00	2.00	Operational
14,608	AGM_14121	Colewood				0.00	6.51	Operational
14,617	AGM_14131	Colewood				0.00	4.36	Operational
14,624	AGM_14138	Colewood				0.00	4.20	Operational
14,628	AGM_14142	Colewood				0.00	4.96	Operational
14,629	AGM_14143	Colewood				0.00	3.95	Operational
14,632	AGM_14146	Colewood				0.00	3.27	Operational
14,635	AGM_14149	Colewood				0.00	1.00	Operational
14,651	AGM_14165	Colewood				0.00	3.90	Operational
14,838	AGM_13863	Heards				0.00	1.50	Operational
14,846	AGM_13871	Heards				0.00	2.50	Operational
14,868	AGM_14359	O13				0.00	0.00	Buried
14,878	AGM_14369	Heards				0.00	5.60	Operational
14,880	AGM_14371	Heards				0.00	1.24	Operational
14,893	AGM_14385	Heards				0.00	3.31	Operational
14,903	AGM_14395	Heards				0.00	5.43	Operational
14,909	AGM_14401	Heards				0.00	0.00	Operational
14,915	AGM_14407	Heards				0.00	2.00	Operational
14,917	AGM_14409	Heards				0.00	0.00	Buried
14,929	AGM_14421	Heards				0.00	2.03	Operational
14,949	AGM_14441	Heards				0.00	5.76	Operational
14,982	AGM_13249	T18				0.00	2.60	Operational
14,985	AGM_13252	T18				0.00	1.85	Operational
14,994	AGM_13260	T18				0.00	3.00	Operational
15,017	AGM_14194	T17				0.00	2.34	Operational
15,030	AGM_14306	T17				0.00	0.00	Operational
15,153	AGM_13360	T18				0.00	4.73	Operational
15,161	AGM_13368	T18				0.00	3.07	Operational
15,209	AGM_13416	T18				0.00	1.50	Operational
15,231	AGM_13438	T18				0.00	1.64	Operational
15,240	AGM_13447	T18				0.00	1.97	Operational
15,242	AGM_13449	T18				0.00	2.74	Operational
15,298	AGM_14214	T17				0.00	4.03	Operational

Structure Inventory Summary Report

10/31/2018

3:02 PM

Rec #:	Structure Number:	Basin:	Type:	Location:	Surface Type:	Rim Elevation:	Depth(ft):	Status:
15,318	AGM_14234	T17				0.00	1.50	Operational
15,321	AGM_14237	T17				0.00	5.83	Operational
15,329	AGM_14245	T17				0.00	5.37	Operational
15,346	AGM_14262	T17				0.00	4.99	Operational
15,364	AGM_14280	O14					1.48	Operational
15,517	AGM_15222	Marsh					1.50	Operational
15,540	AGM_15245	Marsh				0.00	4.81	Operational
15,550	AGM_15255	Marsh				0.00	1.50	Operational
15,600	AGM_14515	T15					0.00	Operational
15,604	AGM_14519	O11				0.00	3.31	Operational
15,611	AGM_14526	T15				0.00	4.75	Operational
15,615	AGM_14530	T15				0.00	9.39	Operational
15,617	AGM_14532	T15				0.00	9.52	Operational
15,639	AGM_14484	O11				0.00	0.00	Buried
15,648	AGM_14493	Marsh				0.00	1.50	Not Found
15,666	AGM_13919	T16				0.00	2.62	Operational
15,688	AGM_13941	T16				0.00	2.50	Operational
15,692	AGM_13945	T16				0.00	1.50	Operational
15,693	AGM_13946	T16				0.00	2.10	Operational
15,710	AGM_13963	T16				0.00	2.80	Operational
15,711	AGM_13964	T16					4.00	Operational
15,712	AGM_13965	T16				0.00	2.40	Operational
15,726	AGM_14000	T16				0.00	3.30	Operational
15,739	AGM_14013	T16				0.00	2.00	Operational
15,755	AGM_14029	T16				0.00	2.50	Operational
15,777	AGM_13890	O12				0.00	3.24	Operational
15,833	AGM_15918	Marsh				0.00	2.00	Operational
15,835	AGM_15920	Marsh				0.00	1.65	Operational
15,839	AGM_15924	Marsh				0.00	1.65	Operational
15,841	AGM_15926	Marsh				0.00	2.00	Operational
15,860	AGM_15945	Marsh				0.00	1.50	Operational
15,861	AGM_15946	Marsh				0.00	1.40	Operational
15,872	AGM_15957	Marsh				0.00	4.10	Operational

Structure Inventory Summary Report

10/31/2018

3:02 PM

Rec #:	Structure Number:	Basin:	Type:	Location:	Surface Type:	Rim Elevation:	Depth(ft):	Status:
15,890	AGM_15975	Marsh				0.00	1.50	Operational
15,910	AGM_15995	Marsh				0.00	8.20	Operational
15,919	AGM_16004	Marsh				0.00	2.00	Operational
15,923	AGM_16008	Marsh				0.00	3.50	Operational
15,929	AGM_16014	Marsh				0.00	2.00	Operational
15,934	AGM_16018	Marsh				0.00	3.50	Operational
15,941	AGM_16026	Marsh				0.00	2.75	Operational
16,001	AGM_12919	Colewood				0.00	2.00	Operational
16,005	AGM_12923	Colewood				0.00	2.00	Operational
16,011	AGM_12929	Colewood				0.00	1.50	Operational
16,026	AGM_12944	Colewood				0.00	3.00	Operational
16,119	AGM_13061	Colewood				0.00	3.81	Operational
16,122	AGM_13064	Colewood				0.00	2.40	Operational
16,126	AGM_13128	Colewood				0.00	3.52	Operational
16,127	AGM_13129	Colewood				0.00	1.50	Operational
16,134	AGM_13136	Colewood				0.00	3.66	Operational
16,151	AGM_13154	Colewood				0.00	3.91	Operational
16,153	AGM_13156	Colewood				0.00	2.00	Operational
16,185	AGM_13098	Colewood				0.00	3.01	Operational
16,212	AGM_13513	Colewood				0.00	2.10	Operational
16,220	AGM_13110	Colewood				0.00	5.28	Operational
16,240	AGM_12871	Colewood				0.00	5.81	Operational
16,241	AGM_12872	Colewood				0.00	4.70	Operational
16,248	AGM_12879	Colewood				0.00	1.50	Operational
16,254	AGM_12885	Colewood				0.00	2.00	Operational
16,376	AGM_14613	Marsh				0.00	1.50	Operational
16,517	AGM_16581	T14				0.00	5.45	Operational
16,601	AGM_16667	T14				0.00	2.68	Operational
16,616	AGM_16682	T14				0.00	3.12	Operational
16,906	AGM_15796	T15				0.00	3.10	Operational
16,907	AGM_15797	T15				0.00	2.71	Operational
16,911	AGM_15801	T15				0.00	2.34	Operational
16,918	AGM_15808	T15				0.00	2.18	Operational

Structure Inventory Summary Report

10/31/2018

3:02 PM

Rec #:	Structure Number:	Basin:	Type:	Location:	Surface Type:	Rim Elevation:	Depth(ft):	Status:
16,930	AGM_15820	T15				0.00	2.00	Operational
17,052	AGM_15338	Marsh				0.00	2.00	Operational
17,055	AGM_15341	Marsh				0.00	1.50	Operational
17,057	AGM_15343	Marsh				0.00	1.50	Operational
17,075	AGM_15362	Marsh				0.00	2.00	Operational
17,097	AGM_15384	T15				0.00	1.50	Operational
17,099	AGM_15386	Marsh				0.00	2.52	Operational
17,102	AGM_15389	Marsh				0.00	2.00	Not Found
17,160	AGM_27598	Marsh				0.00	1.50	Operational
17,181	AGM_28620	Marsh				0.00	2.00	Operational
17,200	AGM_28639	Marsh				0.00	3.15	Operational
17,217	AGM_28656	Marsh				0.00	1.50	Operational
17,241	AGM_28680	Marsh				0.00	1.50	Operational
17,250	AGM_28689	Marsh				0.00	2.00	Operational
17,258	AGM_28697	Marsh				0.00	2.00	Operational
17,267	AGM_28706	Marsh				0.00	2.55	Operational
17,944	AGM_16814	Marsh					1.50	Operational
18,263	AGM_19525	T12				0.00	3.13	Operational
18,379	AGM_19641	T12					1.50	Operational
18,381	AGM_19643	T12					0.00	Operational
18,384	AGM_19646	T12					0.00	Operational
18,591	AGM_23464	T12				0.00	2.60	Operational
18,600	AGM_23473	T12				0.00	3.56	Operational
18,713	AGM_23587	T12				0.00	1.50	Operational
18,744	AGM_16706	O8				0.00	3.77	Operational
18,750	AGM_16712	O8				0.00	2.70	Operational
19,326	AGM_13577	Marsh				0.00	2.97	Operational
19,330	AGM_13581	Marsh				0.00	4.25	Operational
19,332	AGM_13583	Marsh				0.00	5.08	Operational
19,333	AGM_13584	Marsh				0.00	3.25	Operational
19,334	AGM_13585	Marsh				0.00	3.38	Operational
19,353	AGM_13553	Marsh				0.00	1.50	Operational
19,359	AGM_13559	Marsh				0.00	1.50	Operational

Structure Inventory Summary Report

10/31/2018

3:02 PM

Rec #:	Structure Number:	Basin:	Type:	Location:	Surface Type:	Rim Elevation:	Depth(ft):	Status:
19,363	AGM_13563	Marsh				0.00	2.06	Operational
19,368	AGM_13568	Marsh				0.00	1.50	Operational
19,545	AGM_17144	O8				0.00	2.20	Operational
19,547	AGM_16999	T10				0.00	1.50	Operational
19,566	AGM_16274	Ball Mill				0.00	2.60	Operational
19,639	AGM_16433	T12				0.00	3.51	Operational
19,725	AGM_16459	T5				0.00	2.71	Operational
19,853	AGM_17809	Marsh				0.00	1.50	Operational
19,945	AGM_17901	Marsh				0.00	3.50	Operational
19,955	AGM_17911	Marsh				0.00	4.10	Operational
19,957	AGM_17913	Marsh				0.00	1.50	Operational
19,977	AGM_17932	Marsh				0.00	2.00	Operational
19,984	AGM_17939	Marsh				0.00	2.40	Operational
19,986	AGM_17941	Marsh				0.00	2.30	Operational
19,992	AGM_17947	Marsh				0.00	2.00	Operational
21,509	AGM_21122	Marsh				0.00	8.00	Operational
21,512	AGM_21125	Marsh				0.00	2.60	Operational
21,517	AGM_21130	Marsh				0.00	3.20	Operational
21,530	AGM_21143	Marsh				0.00	0.00	Operational
21,536	AGM_21149	Marsh				0.00	2.82	Operational
21,537	AGM_21150	Marsh				0.00	4.05	Operational
21,541	AGM_21154	Marsh				0.00	2.75	Operational
21,618	AGM_26516	Marsh					2.02	Operational
21,678	AGM_21208	Marsh				0.00	2.67	Operational
21,799	AGM_21329	Marsh				0.00	2.20	Operational
22,240	AGM_26725	Marsh					2.40	Operational
22,250	AGM_26735	Marsh					3.80	Operational
22,252	AGM_26737	Marsh					3.90	Operational
22,268	AGM_26753	Marsh					2.73	Operational
22,273	AGM_26758	Marsh					4.85	Operational
22,288	AGM_26773	Marsh				0.00	4.50	Operational
22,293	AGM_26778	Marsh				0.00	2.83	Operational
22,296	AGM_26781	Marsh				0.00	3.80	Operational

Structure Inventory Summary Report

10/31/2018

3:02 PM

Rec #:	Structure Number:	Basin:	Type:	Location:	Surface Type:	Rim Elevation:	Depth(ft):	Status:
23,086	AGM_08969	Long Isl					1.50	Not Found
23,090	AGM_08973	Long Isl					3.00	Operational
23,272	AGM_23182	T12					3.50	Operational
23,297	AGM_23207	T12					3.98	Operational
23,816	AGM_25419	T14					3.10	Operational
23,830	AGM_25433	T14					3.50	Operational
23,836	AGM_25440	T14					4.98	Operational
24,140	AGM_04181	Nancy				0.00	1.50	Operational
24,211	AGM_04257	Nancy					3.50	Operational
24,312	AGM_24949	Nancy				0.00	1.00	Operational
24,453	AGM_15568	Marsh				0.00	1.50	Operational
24,457	AGM_15572	Marsh				0.00	2.02	Operational
24,519	AGM_19679	Marsh				0.00	1.86	Operational
24,521	AGM_19681	Marsh				0.00	1.50	Operational
24,688	AGM_19850	Marsh				0.00	2.70	Operational
24,741	AGM_15450	Marsh				0.00	2.26	Operational
25,064	AGM_23981	T14				0.00	2.20	Operational
25,068	AGM_23985	T14				0.00	2.46	Operational
25,152	AGM_24200	T14				0.00	2.98	Operational
25,163	AGM_24211	T14				0.00	2.91	Operational
25,168	AGM_23279	T12				0.00	3.04	Operational
25,176	AGM_23287	O9				0.00	1.50	Operational
25,295	AGM_23362	T11				0.00	2.41	Operational
25,385	AGM_23388	T11				0.00	2.63	Operational
25,585	AGM_10364	Long Isl					2.84	Operational
25,587	AGM_10366	Long Isl				0.00	4.50	Operational
26,026	AGM_27060	O15				0.00	2.50	Operational
26,705	AGM_25784	T7				0.00	2.60	Operational
26,765	AGM_25901	O8				0.00	1.50	Operational
26,837	AGM_25973	T8				0.00	1.50	Operational
26,841	AGM_25977	T8				0.00	1.50	Operational
26,941	AGM_20065	O8				0.00	1.50	Operational
26,979	AGM_24002	T14				0.00	3.06	Operational

Structure Inventory Summary Report

10/31/2018

3:02 PM

Rec #:	Structure Number:	Basin:	Type:	Location:	Surface Type:	Rim Elevation:	Depth(ft):	Status:
27,144	AGM_22254	T9				0.00	2.10	Operational
27,366	AGM_24744	T1				0.00	2.78	Operational
27,486	AGM_20980	T1				0.00	1.50	Operational
27,489	AGM_20983	T1				0.00	1.50	Operational
27,506	AGM_21000	T1					2.46	Operational
27,507	AGM_21001	T1					2.89	Operational
27,510	AGM_21004	T1				0.00	1.50	Operational
27,532	AGM_21026	T2				0.00	3.68	Operational
27,535	AGM_21029	T2				0.00	5.57	Operational
27,559	AGM_21053	T2				0.00	2.56	Operational
27,572	AGM_21066	T2				0.00	2.63	Operational
27,619	AGM_19914	O4				0.00	0.00	Buried
27,636	AGM_19932	O4				0.00	3.11	Operational
27,673	AGM_19270	T4				0.00	4.56	Operational
27,693	AGM_19290	T4				0.00	2.50	Operational
27,699	AGM_19296	T4				0.00	0.00	Operational
27,700	AGM_19297	T4				0.00	4.53	Operational
27,723	AGM_19320	T3				0.00	5.70	Operational
27,748	AGM_19344	T4				0.00	4.05	Operational
27,753	AGM_19349	T4				0.00	4.25	Operational
27,758	AGM_19354	T4				0.00	3.01	Operational
27,763	AGM_19359	T4				0.00	1.50	Operational
27,864	AGM_21613	T4					2.00	Operational
27,872	AGM_21621	Ball Mill				0.00	3.12	Operational
27,910	AGM_18910	T5					3.00	Operational
27,925	AGM_18925	T5				0.00	2.03	Operational
27,930	AGM_18930	T5				0.00	2.50	Operational
27,955	AGM_18955	O5					1.50	Operational
27,962	AGM_18962	Ball Mill				0.00	3.05	Operational
27,989	AGM_18989	T5				0.00	2.50	Operational
27,999	AGM_18424	O5				0.00	4.68	Operational
28,003	AGM_18428	Ball Mill				0.00	2.05	Operational
28,006	AGM_18431	Ball Mill				0.00	1.50	Operational

Structure Inventory Summary Report

10/31/2018

3:02 PM

Rec #:	Structure Number:	Basin:	Type:	Location:	Surface Type:	Rim Elevation:	Depth(ft):	Status:
28,009	AGM_18434	O5				0.00	3.42	Operational
28,017	AGM_18442	Ball Mill				0.00	2.50	Buried
28,019	AGM_18444	O5				0.00	1.50	Operational
28,023	AGM_18448	Ball Mill					2.77	Operational
28,027	AGM_18452	Ball Mill				0.00	1.25	Operational
28,028	AGM_18453	Ball Mill				0.00	1.25	Operational
28,042	AGM_18364	O5				0.00	2.63	Operational
28,055	AGM_18377	Ball Mill				0.00	5.55	Operational
28,068	AGM_18390	Ball Mill				0.00	4.13	Operational
28,074	AGM_18396	T4				0.00	2.20	Operational
28,075	AGM_18397	T4				0.00	3.23	Operational
28,091	AGM_18413	Ball Mill				0.00	4.98	Operational
28,099	AGM_18422	Ball Mill				0.00	2.50	Operational
28,102	AGM_18465	Ball Mill				0.00	1.50	Operational
28,106	AGM_18469	Ball Mill				0.00	2.00	Operational
28,109	AGM_18472	Ball Mill				0.00	2.00	Buried
28,112	AGM_18475	Ball Mill				0.00	1.25	Operational
28,127	AGM_18488	O5				0.00	2.78	Operational
28,155	AGM_22341	T9				0.00	2.60	Operational
28,158	AGM_17111	T10				0.00	2.84	Operational
28,246	AGM_18531	T3				0.00	2.50	Operational
28,272	AGM_18557	T4				0.00	0.00	Not Found
28,281	AGM_18566	T4				0.00	2.78	Operational
28,315	AGM_19188	O4				0.00	2.50	Operational
28,360	AGM_19233	O4				0.00	2.40	Operational
28,363	AGM_19236	O4				0.00	0.00	Not Found
28,373	AGM_18302	T5				0.00	2.56	Operational
28,378	AGM_18307	O5				0.00	2.41	Operational
28,381	AGM_18310	T5				0.00	2.57	Operational
28,385	AGM_18314	O5				0.00	1.75	Operational
28,460	AGM_21696	T5					2.69	Operational
28,461	AGM_21697	T5					3.30	Operational
28,469	AGM_21705	T6					2.58	Operational

Structure Inventory Summary Report

10/31/2018

3:02 PM

Rec #:	Structure Number:	Basin:	Type:	Location:	Surface Type:	Rim Elevation:	Depth(ft):	Status:
28,504	AGM_21740	T5					2.55	Operational
28,556	AGM_21792	T5				0.00	0.00	Operational
28,634	AGM_20060	T5					3.16	Operational
28,817	AGM_21956	T5				0.00	3.54	Operational
28,826	AGM_21965	T5				0.00	3.76	Operational
29,337	AGM_26411	T9				0.00	2.20	Operational
29,662	AGM_17036	T10					4.58	Operational
29,764	AGM_17043	O8				0.00	4.07	Operational
29,839	AGM_18669	Marsh				0.00	4.22	Operational
29,859	AGM_17013	O8				0.00	4.55	Operational
29,861	AGM_17015	O8				0.00	2.70	Operational
29,865	AGM_17019	O8				0.00	4.20	Operational
29,940	AGM_18655	Marsh				0.00	3.50	Operational
29,955	AGM_18679	Marsh				0.00	2.00	Operational
29,966	AGM_18690	Marsh				0.00	6.77	Operational
29,982	AGM_18723	Marsh				0.00	4.16	Operational
29,984	AGM_18725	Marsh				0.00	1.50	Operational
30,078	AGM_27127	T18				0.00	2.90	Operational
30,169	AGM_27217	T18				0.00	3.30	Operational
30,313	AGM_27415	O15				0.00	2.83	Operational
30,431	AGM_20199	T1				0.00	2.78	Operational
30,492	AGM_27234	T18				0.00	2.67	Operational
30,667	AGM_20295	T1				0.00	5.10	Operational
30,692	AGM_20334	T1				0.00	4.32	Operational
30,715	AGM_20091	Crooked				0.00	1.50	Operational
30,728	AGM_20104	Crooked				0.00	3.01	Operational
30,729	AGM_20105	Crooked				0.00	2.34	Operational
30,734	AGM_20110	Crooked				0.00	2.55	Operational
30,778	AGM_20154	T1				0.00	4.26	Operational
30,782	AGM_20158	T1					2.39	Operational
30,789	AGM_20166	Crooked				0.00	1.50	Operational
30,791	AGM_20168	Crooked				0.00	1.50	Operational
30,799	AGM_20176	Crooked				0.00	1.50	Operational

Structure Inventory Summary Report

10/31/2018

3:02 PM

Rec #:	Structure Number:	Basin:	Type:	Location:	Surface Type:	Rim Elevation:	Depth(ft):	Status:
30,858	AGM_20009	Crooked				0.00	2.02	Operational
30,879	AGM_20029	Crooked				0.00	1.61	Operational
30,880	AGM_20030	Crooked				0.00	1.78	Operational
31,032	AGM_20419	T1				0.00	2.67	Operational
31,173	AGM_20718	T1				0.00	3.85	Operational
31,234	AGM_20347	T1				0.00	0.00	Operational
31,271	AGM_20477	T1				0.00	1.50	Operational
31,293	AGM_20499	T1				0.00	4.14	Operational
31,300	AGM_20506	T1				0.00	0.00	Operational
31,309	AGM_20515	T1				0.00	1.67	Operational
31,311	AGM_20517	T1				0.00	2.77	Operational
31,313	AGM_20519	T1				0.00	2.52	Operational
31,315	AGM_20521	T1				0.00	0.00	Operational
31,329	AGM_20535	T1				0.00	5.00	Operational
31,343	AGM_20549	T1				0.00	3.16	Operational
31,344	AGM_20550	T1				0.00	0.00	Operational
31,354	AGM_20775	T1				0.00	2.75	Operational
31,356	AGM_20777	T1				0.00	3.43	Operational
31,420	AGM_20841	T1				0.00	1.56	Operational
31,444	AGM_20865	T1				0.00	3.80	Operational
31,582	AGM_19032	T1					4.87	Operational
31,586	AGM_19036	T1					3.45	Operational
31,659	AGM_19166	T2				0.00	3.35	Operational
31,781	AGM_18286	Ball Mill				0.00	0.00	Not Found
31,807	AGM_18879	T1					2.12	Operational
31,866	AGM_18230	Ball Mill				0.00	2.93	Operational
31,888	AGM_18252	Ball Mill				0.00	0.00	Operational
32,191	AGM_20439	T1				0.00	0.00	Operational
32,197	AGM_20445	T1				0.00	1.18	Operational
32,252	SSG_00034	T18				0.00	0.00	Operational
32,699	SSG_00596							Operational
32,958	SSG_00855							None
