Weekly Report #7

September 13th, 2023

*****CURRENT CONSTRUCTION ACTIVITIES

LAST WEEK

- Continued Setting Structural Steel and Decking at the Apparatus Bay
- Continued Interior and Exterior CMU Walls
- Continued MEP Interior Wall Rough-in
- Continued MEP Overhead Rough-in at the First Floor
- Layout of Cold-Formed Interior Walls at the Second Floor

THIS WEEK

- Continue MEP in-wall Rough-in
- Continue MEP Overhead Rough-in at the First Floor
- Continue Interior and Exterior CMU Walls



Weekly Report #7

September 13th, 2023

♣ JOBSITE PHOTOS



Continuing Structural Steel at Apparatus Bay Roof



Weekly Report #7

September 13th, 2023




Continuing Installation of Exterior CMU at the Electrical / Generator Rooms



Weekly Report #7

September 13th, 2023



Continuing MEP Overhead Rough-in at the First Floor

Weekly Report #7


September 13th, 2023

★ WEATHER

Weather delays last week: 0							
	3 O	4	5	6	7	8	9
	*	*	*	*	***	*	*
	88°	91°	89°	91°	90°	86°	85°
	64°	67°	67°	70°	64°	66°	63°
	10	11	12	13	14	15	16
	**	*	-	*	-	****	*
	85°	92°	86°	84°	77°	78°	79°
	66°	69°	68°	67°	65°	63°	64°

***** MANPOWER

✓ MANPOWER GRAPH





Weekly Report #7

September 13th, 2023

★ SAFETY REPORT

Days without an accident: 107

• Days without lost time: 107

★ MILESTONE TRACKING

• Construction Start: April 10, 2023

• Current Contract Completion Date: June 10, 2024