Weekly Report #5

October 18th, 2023

TOTAL CONSTRUCTION ACTIVITIES

THIS WEEK - WEEK ENDING 10/21/2023

- Complete joist augmentation on level 3.
- Continue overhead MEP rough-in on level 3.
- Begin joist augmentation on level 2.
- Continue demolition of existing walls and overhead MEP on level 1.
- Begin sprinkler demolition on level 1.
- Heavy Civil crew will mobilize to begin clearing/grubbing and phase 1 erosion control.

NEXT WEEK - WEEK ENDING 10/28/2023

- Begin MEP overhead rough-in on level 3
- Begin wall layout on level 3.
- Continue joist augmentation on level 2.
- Continue demolition of existing walls and overhead MEP on level 1.
- Continue clearing and grubbing the site.
- Begin asphalt demolition.

Weekly Report #5

October 18th, 2023

★ JOBSITE PHOTOS




Overhead MEP Rough-in On Level 3



Weekly Report #5

October 18th, 2023



Demolition Of Interior Walls/Ceilings/Flooring



Weekly Report #5

October 18th, 2023



Complete Joist Augmentation On Level 3

Weekly Report #5

October 18th, 2023




Clearing And Grubbing Of The Site

Weekly Report #5

October 18th, 2023



Clearing And Grubbing Of The Site



Weekly Report #5

October 18th, 2023



Weather delays last week: 0

	and the state of t					
15	16	17	18	19	20	21
	7	*	*	*	7	*
64°	57°	66°	70°	70°	67°	70°
43°	42°	43°	47°	54°	48°	48°
22	23 O	24 O	25 O	O 26	27	28
*	*	*	*	*	*	*
71 °	69°	68°	69°	71 °	72°	69°
46°	47°	48°	51°	57°	58°	52°

Weekly Report #5

October 18th, 2023

★ SAFETY REPORT

• Days without an accident: 37

• Days without lost time: 37

★ MILESTONE TRACKING

• Construction Start: August 21, 2023

• Current Contract Completion Date: Mar 14, 2025