

November 6th, 2023

CURRENT CONSTRUCTION ACTIVITIES

LAST WEEK

- Continued MEP Interior Wall Rough-in at First Floor
- Began Window Installation on First and Second Floor
- Began Below Grade Brick Installation
- Completed Steel Railing Installation at Second Floor Porch
- Continued Overhead Drywall Installation on Second Floor
- Began Second Floor Interior Framing
- Began Second Floor Duct Work Installation.
- Completed Steel Framing for Apparatus Bay Doors

THIS WEEK

- Continue Interior Wall Framing at Second Floor
- Continue Overhead Duct Work Installation at second Floor
- Continue MEP Interior Rough-in at First and Second Floor
- Continue Brick Masonry Mockup at Spalding Entrance
- Continue Overhead Rough-in at Apparatus Bay
- Begin Backfilling Dirt at Mount Vernan Entrance
- Begin Sheet Rock Install on First Floor Interior Walls



Sandy Springs Fire Station #5 Weekly Report #15

November 6th, 2023

JOBSITE PHOTOS




Completed Metal Railing Installation at Second Floor Porch.

REEVES YOUNG

Sandy Springs Fire Station #5 Weekly Report #15

November 6th, 2023




Began Window Installation on the First and Second Floor.



Sandy Springs Fire Station #5 Weekly Report #15

November 6th, 2023



Continued Second Floor Interior Installation on Second Floor.



November 6th, 2023


WEATHER

Weather delays last week: 0

SUN	MON	TUE	WED	THU	FRI	SAT
29	O 30	O 31	0 1	2	З О	4
	*	*	*	*	*	*
82°	82 °	60 °	55 °	57 °	65 °	71 °
56°	47°	32°	29°	30°	35°	40°
5	6	7	8	9	10	• 11
*	*	*	*	*		
75 °	76 °	7 9°	80°	79 °	69 °	64°
42°	45°	48°	53°	58°	50°	48°

MANPOWER

✓ MANPOWER GRAPH





Sandy Springs Fire Station #5 Weekly Report #15

November 6th, 2023

SAFETY REPORT

- Days without an accident: 150
- Days without lost time: 150

MILESTONE TRACKING

- Construction Start: April 10, 2023
- Current Contract Completion Date: June 10, 2024