Weekly Report #11

December 6th, 2023

TOTAL CONSTRUCTION ACTIVITIES

LAST WEEK - WEEK ENDING 12/02/2023

- Continue electrical overhead rough-in on level 3.
- Begin mechanical PIU/VAV rough-in on level 3.
- Begin mechanical overhead rough-in on level 2.
- Continue joist augmentation on level 1.
- Begin fireproofing on level 1.
- Continue slab demolition on the basement.
- Begin joist augmentation on the basement.
- Begin stair 1 steel installation on the roof.
- Continue exterior demo brick/glass/lintel/kicker.
- Begin installing storm line "A".
- Begin grading at sally port.


THIS WEEK - WEEK ENDING 12/09/2023

- Continue electrical overhead rough-in on level 3.
- Continue mechanical PIU/VAV rough-in on level 3.
- Begin interior framing on level 3.
- Continue mechanical overhead rough-in on level 2.
- Continue slab demolition on the basement.
- Continue joist augmentation on the basement.
- Continue stair 1 steel installation on the roof.
- Continue exterior demo brick/glass/lintel/kicker.
- Continue installing U/G utilities.
- Continue grading at Sally Port.
- Begin preparations for footings at sally port.

Weekly Report #11

December 6th, 2023

★ JOBSITE PHOTOS



Continue Mechanical PIU/VAV Rough-In On Level 3



Weekly Report #11

December 6th, 2023



Continue Grading At Sally Port



Weekly Report #11

December 6th, 2023




Continue Exterior Demo Brick/Glass/Lintel/Kicker - North Face



Weekly Report #11

December 6th, 2023



Continue Exterior Demo Of Brick/Glass/Lintel/Kicker



Weekly Report #11


December 6th, 2023



Joist Augmentation On Level 1

Weekly Report #11

December 6th, 2023




Continue Installing U/G Utilities



Weekly Report #11

December 6th, 2023



Continue Exterior Demo of Brick/Glass/Lintel/Kicker



Weekly Report #11

December 6th, 2023




Mechanical Overhead Rough-in On Level 2



Weekly Report #11

December 6th, 2023



Begin Interior Framing On Level 3



Weekly Report #11

December 6th, 2023



Continue Installing U/G Utilities

Weekly Report #11

December 6th, 2023



Weather delays last week: 0

26	27	28	29	30	1 0	2
-	*	*	*	*		*
47°	49°	50°	55°	59°	53°	64°
39°	34°	25°	31°	43°	50°	61°
3	4	5	6	7	8	9
*	*	6	*	*	*	*
66°	67°		51°	57°	60°	64°
41°	36°	39°	29°	34°	46°	56°

Weekly Report #11

December 6th, 2023



SAFETY REPORT

• Days without an accident: 95

• Days without lost time: 95

★ MILESTONE TRACKING

• Construction Start: August 21, 2023

• Current Contract Completion Date: Mar 14, 2025