Weekly Report #15

December 13th, 2023

★ CURRENT CONSTRUCTION ACTIVITIES

LAST WEEK - WEEK ENDING 12/09/2023

- Begin exterior sheathing.
- Installed interior door frames.
- Begin plumbing wall rough-in.
- Continue interior framing.
- Installed risers for the fuel station.
- Continue installing fuel station vent system.
- Begin running the electrical conduit through the site.
- Tank pad and fuel island canopy was backfilled with stone.
- Exterior framing installed.
- Installed inverts inside of the sanitary sewer.

THIS WEEK - WEEK ENDING 12/16/2023


- Exterior sheathing installed.
- Installed blocking for signage and canopies.
- Continue plumbing interior wall rough-in.
- Begin electrical interior wall rough-in.
- Begin forming and prepping fuel tank pad and fuel island for concrete pour (12/13).

Framers to begin one siding walls.

Weekly Report #15

December 13th, 2023

★ JOBSITE PHOTOS



Tank Pad And Fuel Island Canopy Backfilled With Stone



Weekly Report #15

December 13th, 2023



Exterior Framing Installed



Weekly Report #15

December 13th, 2023



Installed Sanitary Sewer Inverts



Weekly Report #15

December 13th, 2023



Plumbing And Electrical Rough-In



Weekly Report #15

December 13th, 2023



Completed Exterior Sheathing




Weekly Report #15

December 13th, 2023



Continue Forming Fuel Tank Pad And Fuel Island



Weekly Report #15

December 13th, 2023



Weather delays last week: 0						
0		. 0	•		•	•
3	4	5	6	/	8	9
*	*	*	*	*	**	→
66°	67°	58°	53°	59°	62°	56°
41°	36°	41°	28°	34°	49°	53°
10	11	12	13	14	15	16
7	*	(*	*	*	*
59°	51°		58°	55°	54°	55°
31°	30°	31°	38°	31°	37°	45°

Weekly Report #15

December 13th, 2023

SAFETY REPORT

• Days without an accident: 82

• Days without lost time: 82

★ MILESTONE TRACKING

• Construction Start: August 21, 2023

• Current Contract Completion Date: March 19, 2024