Weekly Report #4

August 23rd, 2023

*****CURRENT CONSTRUCTION ACTIVITIES

LAST WEEK

- Began Setting Structural Steel
- Continued Interior and Exterior CMU Walls
- Poured CIP Lintels at the Apparatus
- Continued MEP Interior Wall Rough-in

THIS WEEK

- Continue Setting Structural Steel
- Continue MEP in-wall Rough-in
- Continue Interior and Exterior CMU Walls
- Pour Steel Diamonds

Weekly Report #4

August 23rd, 2023

♣ JOBSITE PHOTOS



Interior CMU Installation at the First Floor Decon Area



Weekly Report #4

August 23rd, 2023




Continuing Installation of Exterior CMU



Weekly Report #4

August 23rd, 2023



Structural Steel Second Floor


Weekly Report #4

August 23rd, 2023



Weather	delays last wee	k: 1				
13	14	15	16	17	18	19
*	*	-	*	*	**	*
94°	96°	88°	87°	87°	90°	90°
72°	75°	62°	64°	65°	64°	67°
20	21	22	23	24	25 O	O 26
*	*	*	**	***	*	*
93°	95°	97°	92°	94°	97°	98°
71°	72°	76°	72°	74°	75°	74°

***** MANPOWER





Weekly Report #4

August 23rd, 2023

★ SAFETY REPORT

• Days without an accident: 92

• Days without lost time: 92

★ MILESTONE TRACKING

• Construction Start: April 10, 2023

• Current Contract Completion Date: June 10, 2023