Weekly Report #20

February 7th, 2024

LURRENT CONSTRUCTION ACTIVITIES

LAST WEEK - WEEK ENDING 02/03/2024

- Plumbing & Electrical O/H & In-wall R/I Level 3
- MEP O/H R/I Level 2
- Mechanical & Electrical O/H R/I Level 1
- Mechanical O/H R/L Basement
- · Relocation of fire lines that conflicted with structure and/or HVAC duct
- · Existing plumbing stack line remediation
- Joist web member & beam augmentation Level 1,2,3
- Interior & exterior framing/sheathing
 - Exterior Plan North elevation & radiuses
 - Interior Level 2
- Completed installation of geo-fabric, 57 stone, & 96" perforated CMP for 160'x21' detention pond
- Main Drilling & Boring conducted test drilling at future Sanitary sewer line location 1/29-1/30 to measure depth and density of present rock. This work was performed under Reeves Young Heavy Civil.
- Additional hand rails installed as needed Level 1

THIS WEEK - WEEK ENDING 02/10/2024


- Plumbing & Electrical O/H & in-wall R/I Level 3
- Mechanical tie -in (PIU-VAV) Level 3
- MEP O/H R/I Levels 1 & 2
- Existing plumbing stack line remediation
- Installing brick lintels/kickers at radiuses & beam augmentation Levels 1,2 & 3
- Interior & exterior framing/sheathing
 - Exterior Plan North / North West elevation & radiuses
 - Interior Level 2
- Continue site utility installation
- Remediation of existing Sanitary Sewer Manholes & piping scheduled to start 2/8/24.
- PM on existing generator scheduled for 2/8/24 with Nixon Power.



Weekly Report #20

February 7th, 2024

★ JOBSITE PHOTOS






In Wall Plumbing Rough-In



Weekly Report #20

February 7th, 2024





Plumbing Rough-In



Weekly Report #20

February 7th, 2024








Mechanical Rough-In



Weekly Report #20

February 7th, 2024




Plumbing Stack Line Rework



Weekly Report #20

February 7th, 2024




Grading/Backfill At Newly Installed Detention Pond



Weekly Report #20

February 7th, 2024



Interior Framing



Weekly Report #20

February 7th, 2024





Exterior Sheathing



Weekly Report #20

February 7th, 2024





Installation Of 96" Underground Detention Pond



Weekly Report #20

February 7th, 2024





Electrical Rough-In

Weekly Report #20

February 7th, 2024



Weather delays this week: 0

28	O 29	30 O	31	1	2	3
	*	*	*	*	*	*
47°	54°	60°	56°	62°	70°	60°
37°	29°	39°	30°	40°	44°	40°
4	5	6	7	8	9	10
***	*	*	*	*	*	***
46°	62°	62°	59°	60°	64°	66°
40°	34°	34°	34°	42°	55°	53°

• Total Weather Delays: 7

Weekly Report #20

February 7th, 2024

SAFETY REPORT

• Days without an accident: 144

• Days without lost time: 144

★ MILESTONE TRACKING

• Construction Start: August 21, 2023

• Current Contract Completion Date: Mar 14, 2025