Weekly Report #22

February 21st, 2024

## **TOTAL CONSTRUCTION ACTIVITIES**

## LAST WEEK - WEEK ENDING 02/17/2024

### Roof

Continue parapet/coping blocking

#### Level 3

- Plumbing Overhead & in-wall rough in
- Electrical Overhead & in-wall rough in
- Exterior Framing/Sheathing
- Beam Augmentation (South Elevation)
- Mechanical Tie-in/Duct insulation
- Installing Brick Lintel/Kicker assembly (North elevation)
- Install hard ceiling grid at new & existing bathrooms
- Coring holes through slab for floor to floor copper line sets for condenser/mini-splits

#### Level 2

- Beam Augmentation (South Elevation)
- Mechanical Tie-in
- Exterior Framing/Sheathing
- Mechanical, Electrical, Plumbing Overhead & in-wall rough in
- Installing Brick Lintel/Kicker assembly (North elevation)
- Demo punch (curtain wall steel at entrance/exit of building)

#### Level 1

- Beam Augmentation (South Elevation)
- Exterior Framing/Sheathing
- Mechanical, Electrical, Plumbing Overhead & in-wall rough in
- Begin Installing Brick Lintel/Kicker assembly (North elevation)
- Set exterior door at elevated catwalk (Northwest elevation)
- Demo existing hand rails at stairs 2&3 (levels 1-3)
- Installing new hand rails stairs 2 & 3 (levels 1-3)
- Demo punch

#### Basement

- Mechanical Overhead & in-wall rough in
- Begin slab cut/removal to replace Under Grounding sanitary sewer piping

### Site Engineering & Xylem

- Tie-in bypass piping, initiate bypass at 9:00 AM 2/14/24
- Set new doghouse manhole over existing sanitary sewer gravity line
- Begin replacing existing gravity sanitary sewer line following bypass tie-in & setting of new doghouse manhole

Weekly Report #22

February 21st, 2024

## THIS WEEK - WEEK ENDING 02/24/2024

#### Roof

- Continue parapet blocking
- Screen wall steel install

#### Level 3

- Plumbing Overhead & in-wall rough in
- Electrical Overhead & in-wall rough in
- Mechanical Tie-in/Duct insulation
- Exterior Framing/ Sheathing
- Installing Brick Lintel/Kicker assembly (South elevation)
- Installing 4x4 tube steel to replace previously demoed "X" bracing at existing bathrooms

#### Level 2

- Mechanical, Electrical, Plumbing Overhead & in-wall rough in
  - Mechanical Tie-in/Duct insulation
  - Exterior Framing/Sheathing
  - Installing Brick Lintel/Kicker assembly (South elevation)
  - Interior Framing

### Level 1

- o Mechanical, Electrical, Plumbing Overhead & in-wall rough in
- Mechanical Tie-in/Duct insulation
- Exterior Framing/Sheathing
- Finish Installing new hand rails Stairs 2&3 (Levels 1-3)
- Demo existing & Install new hand rails Stair 1 (Levels 1-3)
- Begin interior framing

## **Basement**

- Mechanical, Electrical, Plumbing Overhead & in-wall rough in
- Continue Slab cut/removal/replacement of U/G sanitary sewer piping
- Fireproofing (elevator room)

#### Exterior

- Continue installing storm line "C" working towards bio-cell
- Demo mechanical yard a South East side of site
- Begin excavating/forming/setting rebar for courtroom/admin wing footings

## Site Engineering & Xylem


- Setting additional manhole at toe of slope nearest to existing FM to gravity transition manhole
- continue replacing existing gravity sanitary sewer line following bypass tie-in



Weekly Report #22

February 21st, 2024

# **★** JOBSITE PHOTOS




In Wall Plumbing Rough-In



Weekly Report #22

February 21st, 2024




In-Wall Electrical



Weekly Report #22


February 21st, 2024



Electrical Rough-In

Weekly Report #22

February 21st, 2024




Mechanical O/H And R/I - Basement

Weekly Report #22

February 21st, 2024





Brick Lintel Installation (North Elevation)



Weekly Report #22

February 21st, 2024



Parapet Wall Blocking



Weekly Report #22

February 21st, 2024




Mechanical Rough-In - First Floor



Weekly Report #22

February 21st, 2024



U/G Sanitary Sewer Remediation - Basement



Weekly Report #22

February 21st, 2024



Hand Rail Demo And Install

Weekly Report #22

February 21st, 2024




Force Main & Gravity Sewer Bypass



Weekly Report #22

February 21st, 2024



Basement Slab Removal



Weekly Report #22

February 21st, 2024




New Doghouse Manhole Set Over Existing Gravity Sewer Line (Fulton County)



Weekly Report #22

February 21st, 2024



Overhead Mechanical Rough-In



Weekly Report #22

February 21st, 2024




**Duct Insulation** 



Weekly Report #22

February 21st, 2024



Replacing Existing Gravity Sewer Piping

Weekly Report #22

February 21st, 2024

## **★** WEATHER

Weather delays this week: 0 0 11 12 15 13 14 16 Monthly Weather 66° 69° 65° 66° 59° 56° 47° 57° 35° 35° 45° 42° 29° 39° 0 0  $\mathbf{O}$ 0 0  $\bigcirc$  $\bigcirc$ 19 21 22 23 24 18 \* 53° 61° 61° 63° 69° 63° 57° 35° 31° 39° 53° 39° 34° 34°

• Total Weather Delays: 12

Weekly Report #22

February 21st, 2024

# SAFETY REPORT

• Days without an accident: 155

• Days without lost time: 155

## **★** MILESTONE TRACKING

• Construction Start: August 21, 2023

• Current Contract Completion Date: Mar 14, 2025