Weekly Report #27

March 27th, 2024

TOTAL CONSTRUCTION ACTIVITIES

LAST WEEK - WEEK ENDING 03/23/2024

Roof

- Roof demo / New roof install
- MEP R/I as new roof is installed

Level 3

- Exterior Sheathing
- Setting of window frames
- pipe insulation
- Copper lines for rooftop condenser units

Level 2

- Exterior Sheathing
- Setting window frames
- Pipe insulation
- Slab demo for elevator CMU extension

Level 1

- MEP-R/I-O/H & In-wall
- Exterior Framing/Sheathing
- interior framing (curtain wall/store front)
- Slab demo for elevator CMU extension
- CMU courses for holding cell/ elevator area

Basement

- Backfill/Rebar/ slab pour back from U/G plumbing replacement & stair 3 extension 3/18/24
- CMU Courses/ Masonry door installs at holding cell/elevator additions
- Exterior Framing/Sheathing
- Mechanical R/I

Exterior/Sallyport

- Plumbing & electrical R/I at cmu walls/ mechanical block-outs
- Water Proofing exterior Sheathing/ exposed BG masonry & CIP walls (per RFI 071)
- Setting MH C10/ running rcp between MHs
- Begin installing storm line B/ setting MH B2
- Excavate/rebar/pour retaining wall b footings
- Excavate/rebar/pour footings for foundation wall & steel columns at courtroom/admin wing
- Brick ledge North elevation
- Setting sequence 6 steel at Sally port addition

Weekly Report #27

March 27th, 2024

THIS WEEK - WEEK ENDING 03/30/2024

Roof

- Screen wall steel install
- Roof demo / New roof install (completed by 3/29/24)
- MEP R/I as new roof is installed

Level 3

- Setting of window frames
- Copper lines for rooftop condenser units
- Low voltage R/I

Level 2

- Exterior Sheathing
- Setting window frames
- CMU courses for holding cell/ elevator area
- Low voltage R/I

Level 1

- MEP-R/I-O/H & In-wall
- Exterior Framing/Sheathing
- interior framing (curtain wall/store front)
- CMU courses for holding cell/ elevator area
- Low voltage R/I

Basement

- CMU Courses/ Masonry door installs at holding cell/elevator area
- MEP O/H R/I
- Setting additional interior columns/beams

Exterior/Sallyport

- Plumbing & electrical R/I at cmu walls/ mechanical block-outs
- Water Proofing exterior Sheathing/ exposed BG masonry & CIP walls (per RFI 071)
- Back filling around exterior of building after waterproofing was applied (per RFI 071)
- Rebar/formwork/pour retaining wall B
- Rebar/formwork/pour for foundation wall at Court/Admin wing addition
- Setting sequence 6 steel at Sally port addition
- Rebar install/pour portion of slab at sallyport 3/29/24 (weather permitting)
- Under slab electrical R/I at portion of slab planned to pour 3/29/24

Notes

- Received first delivery of Sheetrock for the 3rd floor 3/26/24
- All required inspections for rebar/concrete/steel have been conducted
- City of Sandy Springs performed sheathing inspection 3/25/24

Weekly Report #27

March 27th, 2024

★ JOBSITE PHOTOS





Rebar Formwork For Retaining Wall B



Weekly Report #27

March 27th, 2024



CMU At Elevator Walls



Weekly Report #27

March 27th, 2024



Electrical R/I At CMU Walls



Weekly Report #27

March 27th, 2024



New Roof Install



Weekly Report #27

March 27th, 2024





Setting Sequence 6 Steel



Weekly Report #27

March 27th, 2024






New Roof Install



Weekly Report #27

March 27th, 2024




Footings At Court/Admin Wing Foundation Wall



Weekly Report #27

March 27th, 2024



Copper Line Sets For Rooftop Condenser/Split System Units



Weekly Report #27

March 27th, 2024



Window Frame Installation



Weekly Report #27

March 27th, 2024




In Wall Plumbing R/I (Washing Machine Box)



Weekly Report #27

March 27th, 2024



MEP O/H

Weekly Report #27

March 27th, 2024



Weather delays this week: 0

| 17 | 18 | 19 O | 20 | 21 O | 22 O | 23 |
|-----|---------|-------------|------|---------|-------------|------|
| - | * | * | * | * | *** | * |
| 69° | 57° | 60° | 72° | 78° | 62° | 69° |
| 45° | 30° | 41° | 45° | 56° | 52° | 36° |
| 24 | O 25 | 26 | 27 O | O 28 | 29 O | 30 O |
| * | * | - | * | * | * | * |
| 65° | 63° | 62° | 73° | 67° | 7 1° | 76° |
| 43° | 54° | 50° | 48° | 39° | 46° | 52° |

- Total Weather Delays: 15
- No new delays to report, however we do anticipate a delay due to projected rain fall on 3/26/24. Weather will be documented and reported as necessary.

Weekly Report #27

March 27th, 2024

SAFETY REPORT

• Days without an accident: 180

• Days without lost time: 180

★ MILESTONE TRACKING

• Construction Start: August 21, 2023

• Current Contract Completion Date: Mar 14, 2025